

MAR 14 8 56 AM '66

MAR 14 1 02 PM '66

P&DS

99761-6

NPIC PROJECT NO.

C-O-N-F-I-D-E-N-T-I-A-L
CLASSIFICATIONP&DS
RESPONSIBLE COMPONENT

RECEIPT RB/OS

SUPPORT/SERVICE REQUIREMENT

DISSEMINATED RB/OS

(The following info is required when rqmts are levied by external organizations)

OFFICE _____ DATE OF RQMT _____ CONTROL NO. _____

NPIC DIV/DETACH PROCESSING RQMT _____ PROJ OFF _____ PHONE _____

SUPPORT REQUESTED OF _____ PRIORITY _____ DATE REQUIRED _____

(The following info is required when rqmts are levied for internal support)

25X1

DIV/STAFF P & D S DATE OF RQMT 9 March 1966 CONTROL NO. _____

SUPPORT REQUESTED OF P&DS PROJ OFF _____

PRIORITY _____ DATE REQUIRED 30 June 1967

1. BACKGROUND INFORMATION:

The work requested is in support of a gem. ops : _____ Photo interpretation proj.;
☒ Non-photo interpretation project. It will result in: _____ Hard copy report;
☐ Informal report (memo); ☒ Basic service only.

Project Description: Production Units of Advanced Rhomboid Assembly.

2. SPECIFIC SUPPORT/SERVICE REQUESTED: Support from NPIC will probably consist of:

____ Photographic; _____ Reproduction; _____ Mensuration; _____ Graphics; _____ ADP; _____ Editing;
☒ Other (explain below) -- (Include statement as to estimated amount of work required of support component(s); i.e., number of contact prints, enlargements, boards, etc.)

This project covers the monitoring and inspection of production units of the Advanced Rhomboid Assembly.

3. URGENCY JUSTIFICATION: (If immediate support is required a statement of justification must be made on this form.)

DATE OF COMPLETION _____

C-O-N-F-I-D-E-N-T-I-A-L
CLASSIFICATION

NPIC FM 218 (Revised 5-65)

Declass Review by NGA.

25X1